

12. FPT-Q7-HCM - Task #1247

Thay PCU - Host 31 - Cụm Cluster KH PKH

07-10-2024 13:39 - Tuan Nguyen

Trạng thái:	Closed	Bắt đầu:	07-10-2024
Mức ưu tiên:	Normal	Hết hạn:	12-10-2024
Phân công cho:	Tuan Nguyen	Tiến độ:	100%
Chủ đề:		Thời gian ước lượng:	0:00 giờ
Phiên bản:		Thời gian:	0:00 giờ

Mô tả

CPU 1 - trên Host 31 báo lỗi.
Chuẩn bị cập CPU - 2673 V3 - để thay thế.

The screenshot shows the iLO 4 Integrated Management Log interface. The left sidebar contains navigation options like Information, System Information, iLO Event Log, and Location Discovery Services. The main area displays a table of log entries with columns for ID, Severity, Class, Last Update, Initial Update, Count, and Description. The table lists several errors, including 'Uncorrectable Machine Check Exception' and 'Option ROM POST Error'.

ID	Severity	Class	Last Update	Initial Update	Count	Description
807	Critical	CPU	10/07/2024 01:47	10/07/2024 01:47	1	Uncorrectable Machine Check Exception (Board 0, Processor 1, APIC ID 0x00000000, Bank 0x00000013, Status 0xBE20000000C110A, Address 0x0000000080800000, Misc 0x3CFC381600402086)
806	Critical	PCI Bus	10/07/2024 01:45	10/07/2024 01:45	1	PCI Bus Error (Slot 1, Bus 0, Device 3, Function 0)
805	Warning	POST Message	10/06/2024 14:51	10/06/2024 14:51	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
804	Warning	POST Message	10/03/2024 08:29	10/03/2024 08:29	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
803	Warning	POST Message	10/01/2024 18:53	10/01/2024 18:53	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
802	Warning	POST Message	09/30/2024 21:02	09/30/2024 21:02	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
801	Warning	POST Message	09/28/2024 22:07	09/28/2024 22:07	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
800	Warning	POST Message	09/28/2024 21:49	09/28/2024 21:49	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.
799	Critical	CPU	09/28/2024 03:24	09/28/2024 03:24	1	Uncorrectable Machine Check Exception (Board 0, Processor 1, APIC ID 0x00000000, Bank 0x00000013, Status 0xBE20000000C110A, Address 0x0000000080802000, Misc 0x78FC381600402086)
798	Critical	PCI Bus	09/28/2024 03:22	09/28/2024 03:22	1	PCI Bus Error (Slot 1, Bus 0, Device 3, Function 0)
797	Warning	POST Message	09/28/2024 00:26	09/28/2024 00:26	1	Option ROM POST Error: 1719-Slot 0 Drive Array - A controller failure event occurred prior to this power-up. (Previous lock up code = 0x12) Action: Install the latest controller firmware. If the problem persists, replace the controller.

Lược sử

#1 - 09-10-2024 12:20 - Tuan Nguyen

- Trạng thái thay đổi từ In Progress tới Closed

- Tiến độ thay đổi từ 0 tới 100

Tập tin

clipboard-202410071339-nv8e0.png

131 KB

07-10-2024

Tuan Nguyen