

# 31. GIẢI PHÁP-TESTING - Task #1365

## Tạo template snmp monitor server bb

02-12-2024 16:58 - Minh Pham

<b>Trạng thái:</b>	Closed	<b>Bắt đầu:</b>	02-12-2024
<b>Mức ưu tiên:</b>	Normal	<b>Hết hạn:</b>	09-12-2024
<b>Phân công cho:</b>	Minh Pham	<b>Tiến độ:</b>	0%
<b>Chủ đề:</b>		<b>Thời gian ước lượng:</b>	0:00 giờ
<b>Phiên bản:</b>		<b>Thời gian:</b>	0:00 giờ

### Mô tả

Mục tiêu: Tạo template snmp monitor server bb

Kết quả thực hiện:

Link template snmp monitor server bb:

<https://docs.google.com/spreadsheets/d/1jUOwM7dZMDOr2WcaOoUe9Sjyghr6qPyEvg2M5XEbUp0/edit?usp=sharing>

### Template lấy thông tin server dell r620

<input type="checkbox"/> Host	Name ▲	Last check	Last value	Change	Tags
<input type="checkbox"/>	10.4.7.243_20.1374.5296 CPU1 Temp: Temperature 📊	17s	40 °C	+1 °C	component: tempera... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 CPU1 Temp: Temperature status 📊	17s	ok (3)		component: tempera... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Disk state Solid State Disk 0:1:4 Serial	2m 18s	A RAID configuration has ...		Application: physical... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Disk state Solid State Disk 0:1:5 Serial	2m 18s	A RAID configuration has ...		Application: physical... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Disk Status Solid State Disk 0:1:4 Serial	2m 18s	OK (3)		Application: physical... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Disk Status Solid State Disk 0:1:5 Serial	2m 18s	OK (3)		Application: physical... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Firmware version 📊	16h 12m 17s	2.65.65.65		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Hardware model name 📊	16h 12m 17s	PowerEdge R620		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Hardware serial number 📊	16h 12m 17s	J62LZX1		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 ICMP loss	17s	0 %		component: health component: network Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 ICMP ping	17s	Up (1)		Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 ICMP ping	17s	Up (1)		component: health component: network Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 ICMP response time	17s	0.45ms	+0.033ms	component: health component: network Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Operating system 📊	16h 12m 17s	Windows Server 2019		component: os History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Overall system health status 📊	17s	ok (3)		component: system Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 SNMP agent availability 📊	2s	available (1)		component: health component: network Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 SNMP traps (fallback) 📊				component: network History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System Board Inlet Temp: Temperature 📊	17s	22 °C		component: tempera... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System Board Inlet Temp: Temperature status 📊	17s	ok (3)		component: tempera... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System contact details 📊	4h 12m 17s	"support@dell.com"		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System description 📊	4h 12m 17s			component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System location 📊	4h 12m 17s	"unknown"		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System name 📊	4h 12m 17s	idrac-J62LZX1		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 System object ID 📊	4h 12m 17s	iso.3.6.1.4.1.674.10892.5		component: system History
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Uptime (hardware) 📊	17s	00:00:00		component: system Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 Uptime (network) 📊	17s	32 days, 15:36:41	+00:00:29	component: system Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 VDisk state RAID1	17s	OK (2)		Application: virtualDi... Graph
<input type="checkbox"/>	10.4.7.243_20.1374.5296 VDisk Status RAID1	17s	OK (3)		Application: virtualDi... Graph

### Template lấy thông tin server dell 630

<input type="checkbox"/>	10.0.7.209_19424663	CPU1 Temp: Temperature <sup>?</sup>	41s	46 °C	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	CPU1 Temp: Temperature status <sup>?</sup>	41s	ok (3)	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	CPU2 Temp: Temperature <sup>?</sup>	41s	48 °C	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	CPU2 Temp: Temperature status <sup>?</sup>	41s	ok (3)	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	Disk state Solid State Disk 0:1:0 Serial S45NNA1T849...	41s	The physical disk...	Application: physical...
<input type="checkbox"/>	10.0.7.209_19424663	Disk state Solid State Disk 0:1:1 Serial S45NNC0TC15...	41s	The physical disk...	Application: physical...
<input type="checkbox"/>	10.0.7.209_19424663	Disk Status Solid State Disk 0:1:0 Serial S45NNA1T84...	41s	OK (3)	Application: physical...
<input type="checkbox"/>	10.0.7.209_19424663	Disk Status Solid State Disk 0:1:1 Serial S45NNC0TC1...	41s	OK (3)	Application: physical...
<input type="checkbox"/>	10.0.7.209_19424663	Firmware version <sup>?</sup>	16h 45m 41s	2.85.85.85	component: system
<input type="checkbox"/>	10.0.7.209_19424663	Hardware model name <sup>?</sup>	16h 45m 41s	PowerEdge R630	component: system
<input type="checkbox"/>	10.0.7.209_19424663	Hardware serial number <sup>?</sup>	16h 45m 41s	J1QY1M2	component: system
<input type="checkbox"/>	10.0.7.209_19424663	ICMP loss	41s	0 %	component: health component: netw
<input type="checkbox"/>	10.0.7.209_19424663	ICMP ping	41s	Up (1)	
<input type="checkbox"/>	10.0.7.209_19424663	ICMP ping	41s	Up (1)	component: health component: netw
<input type="checkbox"/>	10.0.7.209_19424663	ICMP response time	41s	0.36ms	component: health component: netw
<input type="checkbox"/>	10.0.7.209_19424663	Operating system <sup>?</sup>	16h 45m 41s	VMware ESXi	component: os
<input type="checkbox"/>	10.0.7.209_19424663	Overall system health status <sup>?</sup>	11s	ok (3)	component: system
<input type="checkbox"/>	10.0.7.209_19424663	SNMP agent availability <sup>?</sup>	24s	available (1)	component: health component: netw
<input type="checkbox"/>	10.0.7.209_19424663	SNMP traps (fallback) <sup>?</sup>			component: network
<input type="checkbox"/>	10.0.7.209_19424663	System Board Inlet Temp: Temperature <sup>?</sup>	41s	22 °C	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	System Board Inlet Temp: Temperature status <sup>?</sup>	41s	ok (3)	component: tempera...
<input type="checkbox"/>	10.0.7.209_19424663	System contact details <sup>?</sup>	4h 30m 39s	"support@dell.com"	component: system
<input type="checkbox"/>	10.0.7.209_19424663	System description <sup>?</sup>	4h 30m 39s		component: system
<input type="checkbox"/>	10.0.7.209_19424663	System location <sup>?</sup>	4h 30m 39s	"unknown"	component: system
<input type="checkbox"/>	10.0.7.209_19424663	System name <sup>?</sup>	4h 30m 39s	idrac-J1QY1M2	component: system
<input type="checkbox"/>	10.0.7.209_19424663	System object ID <sup>?</sup>	4h 30m 39s	iso.3.6.1.4.1.674...	component: system
<input type="checkbox"/>	10.0.7.209_19424663	Uptime (hardware) <sup>?</sup>	11s	00:00:00	component: system
<input type="checkbox"/>	10.0.7.209_19424663	Uptime (network) <sup>?</sup>	11s	120 days 17:48:26 +00:00:20	component: system

Template lấy thông tin server dell 6420

<input type="checkbox"/> Host	Name ▲	Last check	Last value	Change	Tags
<input type="checkbox"/> 10.4.7.81_20.1606.327	CPU1 Temp: Temperature ?	1m 17s	50 °C		component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	CPU1 Temp: Temperature status ?	1m 17s	ok (3)		component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	CPU2 Temp: Temperature ?	1m 17s	35 °C		component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	CPU2 Temp: Temperature status ?	1m 17s	ok (3)		component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Disk state Physical Disk 0:1:0 Serial	3m 17s	The physical disk...		Application: physical...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Disk state Physical Disk 0:1:1 Serial	3m 17s	The physical disk...		Application: physical...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Disk Status Physical Disk 0:1:0 Serial	3m 17s	OK (3)		Application: physical...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Disk Status Physical Disk 0:1:1 Serial	3m 17s	OK (3)		Application: physical...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Firmware version ?	16h 13m 16s			component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	Hardware model name ?	16h 13m 16s	PowerEdge C6420		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	Hardware serial number ?	16h 13m 16s	F7ZVXM2		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	ICMP loss	16s	0 %		component: health component: network
<input type="checkbox"/> 10.4.7.81_20.1606.327	ICMP ping	16s	Up (1)		
<input type="checkbox"/> 10.4.7.81_20.1606.327	ICMP ping	16s	Up (1)		component: health component: network
<input type="checkbox"/> 10.4.7.81_20.1606.327	ICMP response time	16s	0.36ms	-0.11ms	component: health component: network
<input type="checkbox"/> 10.4.7.81_20.1606.327	Inlet Temp: Temperature ?	1m 17s	25 °C	+1 °C	component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Inlet Temp: Temperature status ?	1m 17s	ok (3)		component: tempera...
<input type="checkbox"/> 10.4.7.81_20.1606.327	Operating system ?	16h 13m 16s			component: os
<input type="checkbox"/> 10.4.7.81_20.1606.327	Overall system health status ?	16s	critical (5)		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	SNMP agent availability ?	56s	available (1)		component: health component: network
<input type="checkbox"/> 10.4.7.81_20.1606.327	SNMP traps (fallback) ?				component: network
<input type="checkbox"/> 10.4.7.81_20.1606.327	System contact details ?	4h 28m 16s	"support@dell.com"		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	System description ?	4h 28m 16s			component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	System location ?	4h 28m 16s	"unknown"		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	System name ?	4h 28m 16s	iDRAC-F7ZVXM2		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	System object ID ?	4h 28m 16s	iso.3.6.1.4.1.674....		component: system
<input type="checkbox"/> 10.4.7.81_20.1606.327	Uptime (hardware) ?	16s	00:00:00		component: system

Template lấy thông tin server hp 380

<input type="checkbox"/> Host	Name ▲	Last check	Last value	Change	Tags
<input type="checkbox"/> 10.0.7.45	Ambient: Temperature <sup>?</sup>	19s	24 °C	-1 °C	component: tempera...
<input type="checkbox"/> 10.0.7.45	Ambient: Temperature sensor condition <sup>?</sup>	4h 45m 19s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.45	CPU-0.2: Temperature <sup>?</sup>	4h 45m 19s	40 °C		component: tempera...
<input type="checkbox"/> 10.0.7.45	CPU-0.2: Temperature sensor condition <sup>?</sup>	4h 45m 19s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.45	CPU-0.3: Temperature <sup>?</sup>	5h 25m 18s	40 °C		component: tempera...
<input type="checkbox"/> 10.0.7.45	CPU-0.3: Temperature sensor condition <sup>?</sup>	4h 45m 19s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.45	Hardware model name <sup>?</sup>	4h 45m 19s	ProLiant DL360p ...		component: system
<input type="checkbox"/> 10.0.7.45	Hardware serial number <sup>?</sup>	4h 45m 19s	6CU3505PYC		component: system
<input type="checkbox"/> 10.0.7.45	ICMP loss	18s	0 %		component: health component: network
<input type="checkbox"/> 10.0.7.45	ICMP ping	18s	Up (1)		
<input type="checkbox"/> 10.0.7.45	ICMP ping	18s	Up (1)		component: health component: network
<input type="checkbox"/> 10.0.7.45	ICMP response time	18s	0.26ms	+0.0067ms	component: health component: network
<input type="checkbox"/> 10.0.7.45	Overall system health status <sup>?</sup>	4h 45m 19s	ok (2)		component: system
<input type="checkbox"/> 10.0.7.45	SNMP agent availability <sup>?</sup>	42s	available (1)		component: health component: network
<input type="checkbox"/> 10.0.7.45	SNMP traps (fallback) <sup>?</sup>				component: network
<input type="checkbox"/> 10.0.7.45	System: Temperature status <sup>?</sup>	4h 45m 19s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.45	System contact details <sup>?</sup>	10h 4m 16s			component: system
<input type="checkbox"/> 10.0.7.45	System description <sup>?</sup>	10h 4m 16s	Integrated Lights-...		component: system
<input type="checkbox"/> 10.0.7.45	System location <sup>?</sup>	10h 4m 16s	unknown		component: system
<input type="checkbox"/> 10.0.7.45	System name <sup>?</sup>	10h 4m 16s	ILO6CU3505PYC.		component: system
<input type="checkbox"/> 10.0.7.45	System object ID <sup>?</sup>	10h 4m 16s	iso.3.6.1.4.1.232....		component: system
<input type="checkbox"/> 10.0.7.45	Uptime (hardware) <sup>?</sup>	19s	00:00:00		component: system
<input type="checkbox"/> 10.0.7.45	Uptime (network) <sup>?</sup>	19s	16 days, 15:36:56	+00:00:29	component: system

Template lấy thông tin server hp 360 g9

<input type="checkbox"/>	10.0.7.223_19417708	Ambient: Temperature <sup>?</sup>	38s	25 °C	+1 °C	component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	Ambient: Temperature sensor condition <sup>?</sup>	3h 54m 37s	ok (2)		component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	CPU-0.2: Temperature <sup>?</sup>	3h 54m 37s	40 °C		component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	CPU-0.2: Temperature sensor condition <sup>?</sup>	3h 54m 37s	ok (2)		component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	CPU-0.3: Temperature <sup>?</sup>	3h 54m 37s	40 °C		component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	CPU-0.3: Temperature sensor condition <sup>?</sup>	3h 56m 38s	ok (2)		component: tempera...
<input type="checkbox"/>	10.0.7.223_19417708	Disk 0.1(): Disk size <sup>?</sup>	3h 54m 37s	447.1 GB		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Disk 0.1(): Layout type <sup>?</sup>	3h 54m 38s	RAID-1/RAID-10 (3)		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Disk 0.1(): Status <sup>?</sup>	3h 54m 37s	ok (2)		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Disk State Port 1l Box 1 Bay 1 Serial 50026B726309790B	4m 38s	OK (2)		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Disk State Port 1l Box 1 Bay 2 Serial 50026B725805D7...	4m 38s	OK (2)		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Disk Status Port 1l Box 1 Bay 1 Serial 50026B7263097...	4m 38s	OK (2)		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Disk Status Port 1l Box 1 Bay 2 Serial 50026B725805D...	4m 38s	OK (2)		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Disk Temperature Port 1l Box 1 Bay 1 Serial 50026B72...	4m 38s	35		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Disk Temperature Port 1l Box 1 Bay 2 Serial 50026B72...	4m 38s	36		Application: physical...
<input type="checkbox"/>	10.0.7.223_19417708	Hardware model name <sup>?</sup>	3h 58m 37s	ProLiant DL360 ...		component: system
<input type="checkbox"/>	10.0.7.223_19417708	Hardware serial number <sup>?</sup>	3h 58m 37s	6CU650EMYC		component: system
<input type="checkbox"/>	10.0.7.223_19417708	ICMP loss	37s	0 %		component: health component: network
<input type="checkbox"/>	10.0.7.223_19417708	ICMP ping	37s	Up (1)		component: health component: network
<input type="checkbox"/>	10.0.7.223_19417708	ICMP ping	37s	Up (1)		
<input type="checkbox"/>	10.0.7.223_19417708	ICMP response time	37s	0.29ms	+0.027ms	component: health component: network
<input type="checkbox"/>	10.0.7.223_19417708	Overall system health status <sup>?</sup>	3h 58m 37s	ok (2)		component: system
<input type="checkbox"/>	10.0.7.223_19417708	Port 1l Box 1 Bay 1: Disk size <sup>?</sup>	3h 54m 37s	447.13 GB		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Port 1l Box 1 Bay 1: Physical disk media type <sup>?</sup>	3h 54m 37s	solidState (3)		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Port 1l Box 1 Bay 1: Physical disk model name <sup>?</sup>	3h 54m 37s	KINGSTON		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Port 1l Box 1 Bay 1: Physical disk S.M.A.R.T. status <sup>?</sup>	3h 56m 38s	ok (2)		component: disk component: storage
<input type="checkbox"/>	10.0.7.223_19417708	Port 1l Box 1 Bay 1: Physical disk serial number <sup>?</sup>	3h 54m 37s	50026B7263097...		component: disk component: storage

Template lấy thông tin server hp 360 g10

<input type="checkbox"/> Host	Name ▲	Last check	Last value	Change	Tags
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Ambient Temperature ?	2h 42m 50s	22 °C	+1 °C	component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Ambient Temperature ?	6m 51s	23 °C	+1 °C	component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Ambient: Temperature sensor condition ?	3h 36m 50s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Ambient: Temperature sensor condition ?	3h 36m 50s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	CPU-0.2: Temperature ?	3h 36m 50s	40 °C		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	CPU-0.2: Temperature sensor condition ?	3h 36m 50s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	CPU-0.3: Temperature ?	3h 36m 50s	40 °C		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	CPU-0.3: Temperature sensor condition ?	3h 36m 50s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Hardware model name ?	3h 36m 50s	ProLiant DL360 ...		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Hardware serial number ?	3h 36m 50s	MXQ7500BV8		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	ICMP loss	50s	0 %		component: health component: network
<input type="checkbox"/> 10.0.7.123_20.1343.3...	ICMP ping	50s	Up (1)		component: health component: network
<input type="checkbox"/> 10.0.7.123_20.1343.3...	ICMP response time	50s	0.31ms	+0.047ms	component: health component: network
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Overall system health status ?	2h 20m 51s	ok (2)		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	SNMP agent availability ?	34s	available (1)		component: health component: network
<input type="checkbox"/> 10.0.7.123_20.1343.3...	SNMP traps (fallback) ?				component: network
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System: Temperature status ?	3h 36m 50s	ok (2)		component: tempera...
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System contact details ?	2h 56m 50s			component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System description ?	2h 56m 50s	Integrated Lights-...		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System location ?	2h 56m 50s	unknown		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System name ?	2h 56m 50s	ILOMXQ7500BV8.		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	System object ID ?	2h 56m 50s	iso.3.6.1.4.1.232....		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Uptime (hardware) ?	21s	00:00:00		component: system
<input type="checkbox"/> 10.0.7.123_20.1343.3...	Uptime (network) ?	21s	40 days, 15:39:22	+00:00:30	component: system

Template lấy thông tin server hp SL230s Gen8

<input type="checkbox"/>	10.3.7.156_19412908	Ambient: Temperature <sup>?</sup>	2m 6s	20 °C	+1 °C	component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	Ambient: Temperature sensor condition <sup>?</sup>	3h 44m 6s	ok (2)		component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	CPU-0.2: Temperature <sup>?</sup>	4h 48m 5s	40 °C		component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	CPU-0.2: Temperature sensor condition <sup>?</sup>	3h 44m 6s	ok (2)		component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	CPU-0.3: Temperature <sup>?</sup>	3h 44m 6s	40 °C		component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	CPU-0.3: Temperature sensor condition <sup>?</sup>	3h 44m 6s	ok (2)		component: tempera...
<input type="checkbox"/>	10.3.7.156_19412908	Disk 0.1(): Disk size <sup>?</sup>	3h 44m 6s	400 GB		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Disk 0.1(): Layout type <sup>?</sup>	3h 44m 6s	RAID-1/RAID-10 (3)		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Disk 0.1(): Status <sup>?</sup>	3h 44m 6s	ok (2)		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Disk State Port 1l Bay 1 Serial S3ZLNF0M365597	1m 6s	OK (2)		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Disk State Port 1l Bay 2 Serial S3ZLNF0M365610	1m 6s	OK (2)		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Disk Status Port 1l Bay 1 Serial S3ZLNF0M365597	1m 6s	OK (2)		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Disk Status Port 1l Bay 2 Serial S3ZLNF0M365610	1m 6s	OK (2)		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Disk Temperature Port 1l Bay 1 Serial S3ZLNF0M365597	1m 6s	30		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Disk Temperature Port 1l Bay 2 Serial S3ZLNF0M365610	1m 6s	35		Application: physical...
<input type="checkbox"/>	10.3.7.156_19412908	Hardware model name <sup>?</sup>	3h 49m 6s	ProLiant SL230s ...		component: system
<input type="checkbox"/>	10.3.7.156_19412908	Hardware serial number <sup>?</sup>	3h 49m 6s	2UX32902GX		component: system
<input type="checkbox"/>	10.3.7.156_19412908	ICMP loss	5s	0 %		component: health component: network
<input type="checkbox"/>	10.3.7.156_19412908	ICMP ping	5s	Up (1)		component: health component: network
<input type="checkbox"/>	10.3.7.156_19412908	ICMP ping	5s	Up (1)		
<input type="checkbox"/>	10.3.7.156_19412908	ICMP response time	5s	0.66ms	+0.033ms	component: health component: network
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Disk size <sup>?</sup>	3h 44m 6s	894.25 GB		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Physical disk media type <sup>?</sup>	3h 44m 6s	solidState (3)		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Physical disk model name <sup>?</sup>	3h 44m 6s	SAMSUNG		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Physical disk S.M.A.R.T. status <sup>?</sup>	3h 44m 6s	ok (2)		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Physical disk serial number <sup>?</sup>	3h 44m 6s	S3ZLNF0M365597		component: disk component: storage
<input type="checkbox"/>	10.3.7.156_19412908	Port 1l Bay 1: Physical disk status <sup>?</sup>	3h 44m 6s	ok (2)		component: disk component: storage

## Lược sử

### #1 - 06-12-2024 18:44 - Minh Pham

- Mô tả cập nhật

### #2 - 06-12-2024 18:45 - Minh Pham

- Mô tả cập nhật

### #3 - 09-12-2024 08:52 - Minh Pham

- Tập tin clipboard-202412090852-9lxq2.png được thêm

- Mô tả cập nhật

### #4 - 09-12-2024 08:59 - Minh Pham

- Tập tin clipboard-202412090856-7jhoe.png được thêm

- Tập tin clipboard-202412090859-havqk.png được thêm

- Mô tả cập nhật

### #5 - 09-12-2024 09:05 - Minh Pham

- Tập tin clipboard-202412090904-tgkqv.png được thêm

- Tập tin clipboard-202412090905-db7ne.png được thêm

- Mô tả cập nhật

### #6 - 09-12-2024 09:06 - Minh Pham

- Tập tin clipboard-202412090906-ebe1f.png được thêm

- Mô tả cập nhật

**#7 - 09-12-2024 09:07 - Minh Pham**

- Tập tin clipboard-202412090907-osmot.png được thêm

- Mô tả cập nhật

**#8 - 26-02-2025 15:00 - Minh Pham**

- Trạng thái thay đổi từ In Progress tới Closed

**Tập tin**

clipboard-202412090852-9lxq2.png	107 KB	09-12-2024	Minh Pham
clipboard-202412090856-7jhoe.png	83,5 KB	09-12-2024	Minh Pham
clipboard-202412090859-havqk.png	83,3 KB	09-12-2024	Minh Pham
clipboard-202412090904-tgkqv.png	66,8 KB	09-12-2024	Minh Pham
clipboard-202412090905-db7ne.png	89,9 KB	09-12-2024	Minh Pham
clipboard-202412090906-ebe1f.png	76,3 KB	09-12-2024	Minh Pham
clipboard-202412090907-osmot.png	89,5 KB	09-12-2024	Minh Pham